






Building Capacity for a Centre of Excellence for EO-based monitoring of Natural Disasters

Copernicus EMS: Αξιολόγηση πολλαπλών φυσικών κινδύνων - Σχεδιασμός και Ανάκτηση



Γιάννης Παπουτσής ΙΑΑΔΕΤ Εθνικό Αστεροσκοπείο Αθηνών




The Final BEYOND Workshop 17 May 2016 Athens, Electra Palace



What is Copernicus?


An overview





BEYOND's involvement






The three pillars




Disaster types



Procedural workflow





Risk & Recovery



http://emergency.copernicus.eu/mapping/

Product portfolio

Reference mapping

- Hydrology
- o Transport
- Industry & utilities
- Land cover & physiography

Pre-disaster mapping

- o Hazard
- Vulnerability
- Risk status
- Evacuation plans
- Mitigation measures

Post-disaster mapping

- Hazards
- Changes in vulnerability
- Risk status of new assets
- Detailed damage assessment
- Recovery plans
- o Reconstruction &
- rehabilitation monitoring

Copernicus Risk & Recovery Completed & ongoing projects




- Multiple natural hazard risk assessment Planning and Recovery:
 The Azores Islands
- Multiple natural hazard risk assessment Planning and Recovery:
 Madeira
- Earthquake risk assessment Austria Planning and Recovery
- Post-disaster flood assessment in Bulgaria Planning and Recovery




An example






Azores activationReference mapping






Earthquake






Flood






Flood






Lava flow








Landslides



Azores activationSoil erosion






Coastal erosion



35 5 Av	acom 2	STON MARKE	PALA 0	275-97N GY-100	COMPANY TO THE PARTY OF THE PAR	Glide Number: (NVA) Product N: 1855	Auto-alex D. EMIN O'TE ANTAMATIK, v1. English
Table of Ratings of Azores in terms of coastal erosion hazard							
	1 point	2 point	3 points		1 point	2 point	3 points
Relative sea level rise (best estimate for next 100 years)	< 0 mm/y	Between 0 and 0,40mm/y	>0,40 Mm/Y	Digital Elevation Model	< 5% of the region area lies below 5 meters	Between 5 and 10% of the region area lies below 5 meters	> 10% of the region area lies below 5 meters
Shoreline evolution trend Status	Less than 20% of the shoreline is in erosion	Between 20% and 60% of the shoreline is in erosion	More than 60% of the shoreline is in erosion	Engineered frontage	< 5% of engineered frontage along the regional coastline	Between 5% and 35% of engineered frontage along the regional coastline	> 35% of engineered frontage along the regional coastline
Highest water level	Less than 1,5 meters	Between 1,5 and 3 meters	More than 3 meters	Near shore currents	Distance >100m	Distance 50-100 m	Distance < 50 m
Geological coastal type	> 70% of "likely non erodible segments"	"likely non erodable segments" between 40% and 70%	< 40% of "likely non erodable segments"			Management 33 (3) (3)	
VALUE Transmit							
26 97W	61700	25°TV'N 066 900	005300 2F G V 48				


Tsunami





Tsunami






Major types of structural countermeasures:

- Structural reinforcement of assets (ports & other on-land facilities) [A]
- Construction of defences in order to reduce tsunami & storm surges intrusion (Breakwaters, seawalls, groins, quays, dykes / levees) [B]

Azores activationIntegrated analysis





Remarks



- ✓JRC feedback: users were thrilled!
- ✓ Big data handling (EO, production mapping)
- ✓ Expertise & know-how on EO-based monitoring and risk modeling for multiple natural & manmade disasters
- ✓ Strategic positioning as a key Copernicus Service Provider

Thank you for your attention!



Ioannis Papoutsis: <u>ipapoutsis@noa.gr</u>

Haris Kontoes: kontoes@noa.gr